

## **PERSONAL PROTECTIVE EQUIPMENT POLICY**

**S**urya Nautika Sdn. Bhd in line with our Health, Safety and Environmental Policy is committed to implement Personal Protective Equipment (PPE) Policy. This policy is to provide a clear standard to ensure that personnel encountering hazardous conditions are protected from injury and occupational illness through the correct selection of personnel protective equipment (PPE).

The minimum requirement for the employees and contractor staff on the use of personal protective equipment (PPE) on board are:-

- Company's long sleeves boiler suited (coveralls) must always be worn when working anywhere on board.
- Safety helmets must always be used when on deck and machinery room and working within the barge interior where there is a likelihood of materials falling from above and splashing of harmful liquids or fire sparks.
- Safety shoes or boots must always be worn when on deck, in the machinery room, tanks, enclosed and void spaces.
- Appropriate safety glasses/eye shield/sunshades are to be used when working in an environment exposed to infra-red rays (gas welding), ultra-violet rays (electric welding, sunlight), flying particles (de-rusting, grinding) and chemicals.
- Hand gloves of leather types are to be used for handling rough or sharp edges, rubber or PVC gloves for handling of solvents and chemicals, Kevlar type for kitchen cutting. Wearing of hand gloves during operation of high-speed rotating machinery such as pillar drills, lathes, etc. are prohibited.
- Buoyancy work vests are to be worn when working on an open deck or over side.
- Ear muffers/plugs are to be worn when working in areas exposed to high level of noise.
- Safety harness must be used when working aloft of 2 meters or more or when working over side.
- Any defective PPE are prohibited from use and promptly disposed off

# PERSONAL PROTECTIVE EQUIPMENT POLICY

**F**ast Ship Management Sdn. Bhd in line with our Health, Safety and Environmental Policy is committed to implement Personal Protective Equipment (PPE) Policy. This policy is to provide a clear standard to ensure that personnel encountering hazardous conditions are protected from injury and occupational illness through the correct selection of personnel protective equipment (PPE).

The minimum requirement for the employees and contractor staff on the use of personal protective equipment (PPE) on board are:-

- Company's long sleeves boiler suited (coveralls) must always be worn when working anywhere on board.
- Safety helmets must always be used when on deck and machinery room and working within the barge interior where there is a likelihood of materials falling from above and splashing of harmful liquids of fire sparks.
- Safety shoes or boots must always be worn when on deck, in the machinery room, tanks, enclosed and void spaces.
- Appropriate safety glasses/eye shield/sunshades are to be used when working in an environment exposed to infra-red rays (gas welding), ultra-violet rays (electric welding, sunlight), flying particles (de-rusting, grinding) and chemicals.
- Hand gloves of leather types are to be used for handling rough or sharp edges, rubber or PVC gloves for handling of solvents and chemicals, Kevlar type for kitchen cutting. Wearing of hand gloves during operation of high-speed rotating machinery such as pillar drills, lathes, etc. are prohibited.
- Buoyancy work vests are to be worn when working on an open deck or over side.
- Ear muffers/plugs are to be worn when working in areas exposed to high level of noise.
- Safety harness must be used when working aloft of 2 meters or more or when working over side.
- Any defective PPE are prohibited from use and promptly disposed off

# PERSONAL PROTECTIVE EQUIPMENT POLICY

**F**ast Ship Management Sdn. Bhd in line with our Health, Safety and Environmental Policy is committed to implement Personal Protective Equipment (PPE) Policy. This policy is to provide a clear

standard to ensure that personnel encountering hazardous conditions are protected from injury and occupational illness through the correct selection of personnel protective equipment (PPE).

The minimum requirement for the employees and contractor staff on the use of personal protective equipment (PPE) on board are:-

- Company's long sleeves boiler suited (coveralls) must always be worn when working anywhere on board.
- Safety helmets must always be used when on deck and machinery room and working within the barge interior where there is a likelihood of materials falling from above and splashing of harmful liquids or fire sparks.
- Safety shoes or boots must always be worn when on deck, in the machinery room, tanks, enclosed and void spaces.
- Appropriate safety glasses/eye shield/sunshades are to be used when working in an environment exposed to infra-red rays (gas welding), ultra-violet rays (electric welding, sunlight), flying particles (de-rusting, grinding) and chemicals.
- Hand gloves of leather types are to be used for handling rough or sharp edges, rubber or PVC gloves for handling of solvents and chemicals, Kevlar type for kitchen cutting. Wearing of hand gloves during operation of high-speed rotating machinery such as pillar drills, lathes, etc. are prohibited.
- Buoyancy work vests are to be worn when working on an open deck or over side.
- Ear muffers/plugs are to be worn when working in areas exposed to high level of noise.
- Safety harness must be used when working aloft of 2 meters or more or when working over side.
- Any defective PPE are prohibited from use and promptly disposed off